



CVE-2021-43662

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2021-43662
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2022-03-31 00:15:00 UTC
Updated	2022-07-12 17:42:00 UTC
Description	totolink EX300_v2, ver V4.0.3c.140_B20210429 and A720R ,ver V4.1.5cu.470_B20200911 have an issue which causes un

Risk And Classification

Problem Types: CWE-770

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Totolink	A720r	-	All	All	All
Operating System	Totolink	A720r Firmware	4.1.5cu.470_b20200911	All	All	All
Hardware	Totolink	Ex300 V2	-	All	All	All
Operating System	Totolink	Ex300 V2 Firmware	4.0.3c.140_b20210429	All	All	All

References

Reference	Source	Link	Tags
iot-vuls/dos.md at main · chibataiki/iot-vuls · GitHub	MISC	github.com	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report