




CVE-2021-45995

Published on: Not Yet Published

Last Modified on: 02/08/2022 04:09:00 PM UTC

CVE-2021-45995

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

Certain versions of [G1](#) from [Tendacn](#) contain the following vulnerability:

Tenda routers G1 and G3 v15.11.0.17(9502)_CN were discovered to contain a stack overflow in the function formSetStaticRoute. This vulnerability allows attackers to cause a Denial of Service (DoS) via the staticRouteNet, staticRouteMask, and staticRouteGateway parameters.

CVE-2021-45995 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.5 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	NONE	HIGH

CVSS2 Score: **7.8 - HIGH**

Access Vector	Access Complexity	Authentication
NETWORK	LOW	NONE
Confidentiality Impact	Integrity Impact	Availability Impact
NONE	NONE	COMPLETE

CVE References

Description	Tags	Link
my_vuln/9.md at main · pjqwudi/my_vuln · GitHub	github.com text/html	MISC github.com/pjqwudi/my_vuln/blob/main/Tenda/vuln_9/9.md

By selecting these links, you may be leaving CVEreport webpages. We have provided these links to other websites because they may have information that

There are currently no QIDs associated with this CVE

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tendacn	G1	-	All	All	All
Operating System	Tendacn	G1 Firmware	15.11.0.17\ (9502\)_cn	All	All	All
Hardware	Tendacn	G3	-	All	All	All
Operating System	Tendacn	G3 Firmware	15.11.0.17\ (9502\)_cn	All	All	All
<pre>cpe:2.3:h:tendacn:g1:-:~::~~::~~::~~::~~::~~::~~::</pre>						
<pre>cpe:2.3:o:tendacn:g1_firmware:15.11.0.17\ (9502\)_cn:~::~~::~~::~~::~~::~~::~~::</pre>						
<pre>cpe:2.3:h:tendacn:g3:-:~::~~::~~::~~::~~::~~::~~::</pre>						
<pre>cpe:2.3:o:tendacn:g3_firmware:15.11.0.17\ (9502\)_cn:~::~~::~~::~~::~~::~~::~~::</pre>						

Social Mentions

Source	Title	Posted (UTC)
 @CVEreport	CVE-2021-45995 : Tenda routers G1 and G3 v15.11.0.17 9502_CN were discovered to contain a stack overflow in the fu... twitter.com/i/web/status/1...	2022-02-04 02:26:21
 /r/netcve	CVE-2021-45995	2022-02-04 02:38:19

Next ID→