



CVE-2022-26278

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2022-26278
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2022-03-28 21:15:00 UTC
Updated	2022-04-04 17:17:00 UTC
Description	Tenda AC9 v15.03.2.21_cn was discovered to contain a stack overflow via the time parameter in the PowerSaveSet function

Risk And Classification

Problem Types: CWE-787

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tenda	Ac9	-	All	All	All
Operating System	Tenda	Ac9 Firmware	15.03.2.21_cn	All	All	All

References

Reference

Tenda-AC9-V15.03.2.21_cn-Command-Execution-Vulnerability/Tenda-AC9 at main · pllrry/Tenda-AC9-V15.03.2.21_cn-Command-Execution-Vulnerability
CVE Program record
NVD vulnerability detail

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report