



# CVE-2022-30269

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

## Summary

<b>CVE</b>	CVE-2022-30269
<b>State</b>	PUBLIC
<b>Assigner</b>	cve@mitre.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2022-07-26 23:15:00 UTC
<b>Updated</b>	2022-08-02 20:03:00 UTC
<b>Description</b>	Motorola ACE1000 RTUs through 2022-05-02 mishandle application integrity. They allow for custom application installation

## Risk And Classification

**Problem Types:** CWE-345

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	<a href="#">Motorola</a>	<a href="#">Ace1000</a>	-	All	All	All
Operating System	<a href="#">Motorola</a>	<a href="#">Ace1000 Firmware</a>	-	All	All	All

## References

Reference	Source	Link	Tags
Motorola Solutions ACE1000   CISA	MISC	<a href="http://www.cisa.gov">www.cisa.gov</a>	
Blog - Forescout	MISC	<a href="http://www.forescout.com">www.forescout.com</a>	
CVE Program record	CVE.ORG	<a href="http://www.cve.org">www.cve.org</a>	canonical
NVD vulnerability detail	NVD	<a href="http://nvd.nist.gov">nvd.nist.gov</a>	canonical, analysis

No vendor comments have been submitted for this CVE.

## Legacy QID Mappings

[159984](#) Oracle Enterprise Linux Security Update for ol8addon (ELSA-2022-17957)

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**CVE.report and Source URL Uptime Status [status.cve.report](https://status.cve.report)**