



# CVE-2022-38125

Published on: Not Yet Published

Last Modified on: 04/28/2023 12:56:00 AM UTC

## CVE-2022-38125

Source: Mitre

Source: NIST

CVE.ORG

Print: PDF



Certain versions of [SiteManager 1129](#) from [Secomea](#) contain the following vulnerability:

Improper Restriction of Communication Channel to Intended Endpoints vulnerability in Secomea SiteManager (FTP Agent modules) allows Exploiting Trust in Client.

CVE-2022-38125 has been assigned by VulnerabilityReporting@secomea.com to track the vulnerability - currently rated as **MEDIUM** severity.

Affected Vendor/Software: **Secomea - SiteManager** version <= 10.0

CVSS3 Score: **5.5 - MEDIUM**

| Attack Vector    | Attack Complexity      | Privileges Required | User Interaction    |
|------------------|------------------------|---------------------|---------------------|
| <b>LOCAL</b>     | <b>LOW</b>             | <b>LOW</b>          | <b>NONE</b>         |
| Scope            | Confidentiality Impact | Integrity Impact    | Availability Impact |
| <b>UNCHANGED</b> | <b>HIGH</b>            | <b>NONE</b>         | <b>NONE</b>         |

## CVE References

| Description                      | Tags                                                                                                     | Link                                                                        |
|----------------------------------|----------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------|
| Cybersecurity Advisory - Secomea | <a href="#">web.archive.org</a><br><a href="#">text/html</a><br><b>Inactive Link</b> <b>Not Archived</b> | <b>MISC</b> <a href="#">www.secomea.com/support/cybersecurity-advisory/</a> |

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](mailto:comment@cve.report).

There are currently no QIDs associated with this CVE

| Known Affected Configurations (CPE V2.3)                                                                                                                                         |                         |                                           |         |        |         |          |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|-------------------------------------------|---------|--------|---------|----------|
| Type                                                                                                                                                                             | Vendor                  | Product                                   | Version | Update | Edition | Language |
| Hardware       | <a href="#">Secomea</a> | <a href="#">Sitemanager 1129</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 1129 Firmware</a> | All     | All    | All     | All      |
| Hardware       | <a href="#">Secomea</a> | <a href="#">Sitemanager 1139</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 1139 Firmware</a> | All     | All    | All     | All      |
| Hardware       | <a href="#">Secomea</a> | <a href="#">Sitemanager 1149</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 1149 Firmware</a> | All     | All    | All     | All      |
| Hardware       | <a href="#">Secomea</a> | <a href="#">Sitemanager 1529</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 1529 Firmware</a> | All     | All    | All     | All      |
| Hardware       | <a href="#">Secomea</a> | <a href="#">Sitemanager 1539</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 1539 Firmware</a> | All     | All    | All     | All      |
| Hardware   | <a href="#">Secomea</a> | <a href="#">Sitemanager 1549</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 1549 Firmware</a> | All     | All    | All     | All      |
| Hardware   | <a href="#">Secomea</a> | <a href="#">Sitemanager 3329</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 3329 Firmware</a> | All     | All    | All     | All      |
| Hardware   | <a href="#">Secomea</a> | <a href="#">Sitemanager 3339</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 3339 Firmware</a> | All     | All    | All     | All      |
| Hardware   | <a href="#">Secomea</a> | <a href="#">Sitemanager 3349</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 3349 Firmware</a> | All     | All    | All     | All      |
| Hardware   | <a href="#">Secomea</a> | <a href="#">Sitemanager 3529</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 3529 Firmware</a> | All     | All    | All     | All      |
| Hardware   | <a href="#">Secomea</a> | <a href="#">Sitemanager 3539</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 3539 Firmware</a> | All     | All    | All     | All      |
| Hardware   | <a href="#">Secomea</a> | <a href="#">Sitemanager 3549</a>          | -       | All    | All     | All      |
| Operating System                                                                                                                                                                 | <a href="#">Secomea</a> | <a href="#">Sitemanager 3549 Firmware</a> | All     | All    | All     | All      |

|                                                 |
|-------------------------------------------------|
| cpe:2.3:h:secomea:sitemanager_1129:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_1129_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_1139:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_1139_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_1149:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_1149_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_1529:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_1529_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_1539:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_1539_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_1549:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_1549_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_3329:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_3329_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_3339:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_3339_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_3349:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_3349_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_3529:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_3529_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_3539:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_3539_firmware::~: |
| cpe:2.3:h:secomea:sitemanager_3549:-:~::~:      |
| cpe:2.3:o:secomea:sitemanager_3549_firmware::~: |

No vendor comments have been submitted for this CVE

## Social Mentions

| Source | Title | Posted (UTC) |
|--------|-------|--------------|
|--------|-------|--------------|

[← Previous ID](#)

Next ID→

© [CVE.report](#) 2023   |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**CVE.report and Source URL Uptime Status** [status.cve.report](#)