




CVE-2022-42160

Published on: Not Yet Published

Last Modified on: 10/18/2022 12:15:00 PM UTC

CVE-2022-42160

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

Certain versions of [Covr 1200](#) from [Dlink](#) contain the following vulnerability:

D-Link COVR 1200,1202,1203 v1.08 was discovered to contain a command injection vulnerability via the system_time_timezone parameter at function SetNTPServerSettings.

CVE-2022-42160 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **8.8 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	HIGH	HIGH

CVE References

Description	Tags	Link
vul_discovery/D-Link COVR 12xx .pdf at master · 14isnot40/vul_discovery · GitHub	github.com text/html	MISC github.com/14isnot40/vul_discovery/blob/master/D-Link%20COVR%2012xx%20.pdf
Security Bulletin D-Link	www.dlink.com text/html	MISC www.dlink.com/en/security-bulletin/

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Dlink	Covr 1200	-	All	All	All
Operating System	Dlink	Covr 1200 Firmware	1.08	All	All	All
Hardware 	Dlink	Covr 1202	-	All	All	All
Operating System	Dlink	Covr 1202 Firmware	1.08	All	All	All
Hardware 	Dlink	Covr 1203	-	All	All	All
Operating System	Dlink	Covr 1203 Firmware	1.08	All	All	All
cpe:2.3:h:dlink:covr_1200:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:dlink:covr_1200_firmware:1.08:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:dlink:covr_1202:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:dlink:covr_1202_firmware:1.08:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:h:dlink:covr_1203:-:~::~~::~~::~~::~~::~~::~~::						
cpe:2.3:o:dlink:covr_1203_firmware:1.08:~::~~::~~::~~::~~::~~::~~::						
No vendor comments have been submitted for this CVE						
Social Mentions						
Source	Title					Posted (UTC)
 @CVEreport	CVE-2022-42160 : D-Link COVR 1200,1202,1203 v1.08 was discovered to contain a command injection vulnerability via t... twitter.com/i/web/status/1...					2022-10-13 19:07:36
 @Robo_Alerts	Potentially Critical CVE Detected! CVE-2022-42160 D-Link COVR 1200,1202,1203 v1.08 was discovered to contain a comm... twitter.com/i/web/status/1...					2022-10-13 19:56:00
 /r/netcve	CVE-2022-42160					2022-10-13 20:38:59
← Previous ID			Next ID →			