



CVE-2022-42786

Published on: Not Yet Published

Last Modified on: 01/20/2023 02:53:00 PM UTC

CVE-2022-42786 - advisory for VDE-2022-043

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

Certain versions of [At-modem-emulator](#) from [Wut](#) contain the following vulnerability:

Multiple W&T Products of the ComServer Series are prone to an XSS attack. An authenticated remote Attacker can execute arbitrary web scripts or HTML via a crafted payload injected into the title of the configuration webpage

CVE-2022-42786 has been assigned by [cert](#) info@cert.vde.com to track the vulnerability - currently rated as **MEDIUM** severity.

CVSS3 Score: **5.4 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	LOW	REQUIRED
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
CHANGED	LOW	LOW	NONE

CVE References

Description	Tags	Link
VDE-2022-043 CERT@VDE	cert.vde.com text/html	MISC cert.vde.com/de/advisories/VDE-2022-043/

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](#).

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
------	--------	---------	---------	--------	---------	----------

Category		Product		Availability		
Hardware		Wut	At-modem-emulator	-	All	All
Operating System		Wut	At-modem-emulator Firmware	All	All	All
Hardware		Wut	Com-server 20ma	-	All	All
Operating System		Wut	Com-server 20ma Firmware	All	All	All
Hardware		Wut	Com-server Highspeed 100basefx	-	All	All
Operating System		Wut	Com-server Highspeed 100basefx Firmware	All	All	All
Hardware		Wut	Com-server Highspeed 100baselx	-	All	All
Operating System		Wut	Com-server Highspeed 100baselx Firmware	All	All	All
Hardware		Wut	Com-server Highspeed 19 1port	-	All	All
Operating System		Wut	Com-server Highspeed 19 1port Firmware	All	All	All
Hardware		Wut	Com-server Highspeed 19 4port	-	All	All
Operating System		Wut	Com-server Highspeed 19 4port Firmware	All	All	All
Hardware		Wut	Com-server Highspeed Compact	-	All	All
Operating System		Wut	Com-server Highspeed Compact Firmware	All	All	All
Hardware		Wut	Com-server Highspeed Industry	-	All	All
Operating System		Wut	Com-server Highspeed Industry Firmware	All	All	All
Hardware		Wut	Com-server Highspeed Isolated	-	All	All
Operating System		Wut	Com-server Highspeed Isolated Firmware	All	All	All
Hardware		Wut	Com-server Highspeed Lc	-	All	All
Operating System		Wut	Com-server Highspeed Lc Firmware	All	All	All
Hardware		Wut	Com-server Highspeed Oem	-	All	All
Operating System		Wut	Com-server Highspeed Oem Firmware	All	All	All
Hardware		Wut	Com-server Highspeed Office 1port	-	All	All
Operating System		Wut	Com-server Highspeed Office 1port Firmware	All	All	All
Hardware		Wut	Com-server Highspeed Office 4port	-	All	All
Operating System		Wut	Com-server Highspeed Office 4port Firmware	All	All	All

Hardware	 	Wut	Com-server Highspeed Poe	-	All	All	All
Hardware	 	Wut	Com-server Highspeed Poe 3x Isolated	-	All	All	All
Operating System		Wut	Com-server Highspeed Poe 3x Isolated Firmware	All	All	All	All
Operating System		Wut	Com-server Highspeed Poe Firmware	All	All	All	All
Hardware	 	Wut	Com-server Highspeed UI	-	All	All	All
Operating System		Wut	Com-server Highspeed UI Firmware	All	All	All	All
Hardware	 	Wut	Com-server	-	All	All	All
Operating System		Wut	Com-server Firmware	All	All	All	All
cpe:2.3:h:wut:at-modem-emulator:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:at-modem-emulator_firmware:*~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:h:wut:com-server_20ma:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:com-server_20ma_firmware:*~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:h:wut:com-server_highspeed_100basefx:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:com-server_highspeed_100basefx_firmware:*~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:h:wut:com-server_highspeed_100baselx:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:com-server_highspeed_100baselx_firmware:*~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:h:wut:com-server_highspeed_19\"_1port:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:com-server_highspeed_19\"_1port_firmware:*~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:h:wut:com-server_highspeed_19\"_4port:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:com-server_highspeed_19\"_4port_firmware:*~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:h:wut:com-server_highspeed_compact:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:com-server_highspeed_compact_firmware:*~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:h:wut:com-server_highspeed_industry:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:com-server_highspeed_industry_firmware:*~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:h:wut:com-server_highspeed_isolated:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:com-server_highspeed_isolated_firmware:*~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:h:wut:com-server_highspeed_lc:-:~::~~::~~::~~::~~::~~::~~:::							
cpe:2.3:o:wut:com-server_highspeed_lc_firmware:*~::~~::~~::~~::~~::~~::~~:::							

```
cpe:2.3:o:wut:com-server_\\+_firmware:*:*:*:*:*:*:
```

2022-11-10
12:38:46

Next ID→

CVE.report and Source URL Uptime Status status.cve.report