



CVE-2022-46527

Published on: Not Yet Published

Last Modified on: 09/07/2023 05:32:00 PM UTC

CVE-2022-46527

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#) 

Certain versions of [Ers 1.5](#) from [Elsys](#) contain the following vulnerability:

ELSYS ERS 1.5 Sound v2.3.8 was discovered to contain a buffer overflow via the NFC data parser.

CVE-2022-46527 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **HIGH** severity.

CVSS3 Score: **7.5 - HIGH**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
NETWORK	LOW	NONE	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	NONE	NONE	HIGH

CVE References

Description	Tags	Link
	github.com application/octet-stream	MISC github.com/post-cyberlabs/CVE-Advisory/blob/main/CVE-2022-46527.pdf
ERS Sound – en	www.elsys.se text/html	MISC www.elsys.se/en/ers-sound/

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Elsys	Ers 1.5	-	All	All	All
Operating System	Elsys	Ers 1.5 Firmware	2.3.8	All	All	All
cpe:2.3:h:elsys:ers_1.5:-:*:*:*:*:*:						
cpe:2.3:o:elsys:ers_1.5_firmware:2.3.8:*:*:*:*:*:						
No vendor comments have been submitted for this CVE						
← Previous ID				Next ID →		