



CVE-2023-30937


Published on: Not Yet Published

Last Modified on: 07/20/2023 01:46:00 AM UTC

CVE-2023-30937

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AV:L/AC:L/PR:L/UI:N/S:U/C:H/I:N/A:N



Certain versions of [Android](#) from [Google](#) contain the following vulnerability:

In telephony service, there is a missing permission check. This could lead to local information disclosure with no additional execution privileges needed.

CVE-2023-30937 has been assigned by [security@unisoc.com](#) to track the vulnerability - currently rated as **MEDIUM** severity.

Affected Vendor/Software: [Unisoc \(Shanghai\) Technologies Co., Ltd.](#) -

SC9863A/SC9832E/SC7731E/T610/T310/T606/T760/T618/T606/T612/T616/T760/T770/T820/S8000 version = **Android10/Android11/Android12/Android13**

CVSS3 Score: **5.5 - MEDIUM**

Attack Vector	Attack Complexity	Privileges Required	User Interaction
LOCAL	LOW	LOW	NONE
Scope	Confidentiality Impact	Integrity Impact	Availability Impact
UNCHANGED	HIGH	NONE	NONE

CVE References

Description	Tags	Link
2023-07	www.unisoc.com text/html	MISC www.unisoc.com/en_us/secy/announcementDetail/1676902764208259073

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to comment@cve.report.

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Google	Android	10.0	All	All	All
Operating System	Google	Android	11.0	All	All	All
Operating System	Google	Android	12.0	All	All	All
Operating System	Google	Android	13.0	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	S8000	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	Sc7731e	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	Sc9832e	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	Sc9863a	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	T310	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	T606	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	T610	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	T612	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	T616	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	T618	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	T760	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	T770	-	All	All	All
Hardware 🇹🇼 ↗️	Unisoc	T820	-	All	All	All
cpe:2.3:o:google:android:10.0:*:*:*:*:*:						
cpe:2.3:o:google:android:11.0:*:*:*:*:*:						
cpe:2.3:o:google:android:12.0:*:*:*:*:*:						
cpe:2.3:o:google:android:13.0:*:*:*:*:*:						
cpe:2.3:h:unisoc:s8000:-:*:*:*:*:*:						
cpe:2.3:h:unisoc:sc7731e:-:*:*:*:*:*:						
cpe:2.3:h:unisoc:sc9832e:-:*:*:*:*:*:						
cpe:2.3:h:unisoc:sc9863a:-:*:*:*:*:*:						
cpe:2.3:h:unisoc:t310:-:*:*:*:*:*:						

cpe:2.3:h:unisoc:t606:-:~::~~::~~::~~::~~::~~::~~::
cpe:2.3:h:unisoc:t610:-:~::~~::~~::~~::~~::~~::~~::
cpe:2.3:h:unisoc:t612:-:~::~~::~~::~~::~~::~~::~~::
cpe:2.3:h:unisoc:t616:-:~::~~::~~::~~::~~::~~::~~::
cpe:2.3:h:unisoc:t618:-:~::~~::~~::~~::~~::~~::~~::
cpe:2.3:h:unisoc:t760:-:~::~~::~~::~~::~~::~~::~~::
cpe:2.3:h:unisoc:t770:-:~::~~::~~::~~::~~::~~::~~::
cpe:2.3:h:unisoc:t820:-:~::~~::~~::~~::~~::~~::~~::

No vendor comments have been submitted for this CVE

Social Mentions		
Source	Title	Posted (UTC)
 @CVEreport	CVE-2023-30937 : In telephony service, there is a missing permission check. This could lead to local information di... twitter.com/i/web/status/1...	2023-07-12 09:15:02
← Previous ID		Next ID →