



# CVE-2023-37715


Published on: Not Yet Published

Last Modified on: 07/21/2023 02:33:00 PM UTC

## CVE-2023-37715

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H



Certain versions of [F1202](#) from [Tenda](#) contain the following vulnerability:

Tenda F1202 V1.0BR\_V1.2.0.20(408), FH1202\_V1.2.0.19\_EN were discovered to contain a stack overflow in the page parameter in the function frmL7ProtForm.

CVE-2023-37715 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack  
Vector

Attack  
Complexity

Privileges  
Required

User  
Interaction

**NETWORK**

**LOW**

**NONE**

**NONE**

Scope

Confidentiality  
Impact

Integrity  
Impact

Availability  
Impact

**UNCHANGED**

**HIGH**

**HIGH**

**HIGH**

## CVE References

Description

Tags

Link

Tenda Router  
Vulnerability:F1202,FH1202

[github.com](#)  
[text/plain](#)

[MISC github.com/FirmRec/loT-Vulns/blob/main/tenda/fmL7ProtForm/reprot.md](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](mailto:comment@cve.report).

There are currently no QIDs associated with this CVE

## Known Affected Configurations (CPE V2.3)

| Type | Vendor | Product | Version | Update | Edition | Language |
|------|--------|---------|---------|--------|---------|----------|
|------|--------|---------|---------|--------|---------|----------|

|                                                              |       |                 |                  |     |     |     |
|--------------------------------------------------------------|-------|-----------------|------------------|-----|-----|-----|
| Hardware                                                     | Tenda | F1202           | -                | All | All | All |
| Operating System                                             | Tenda | F1202 Firmware  | 1.0br            | All | All | All |
| Operating System                                             | Tenda | F1202 Firmware  | 1.2.0.20\ (408\) | All | All | All |
| Hardware                                                     | Tenda | Fh1202          | -                | All | All | All |
| Operating System                                             | Tenda | Fh1202 Firmware | 1.2.0.19_en      | All | All | All |
| cpe:2.3:h:tenda:f1202:-:~::~~::~~:::                         |       |                 |                  |     |     |     |
| cpe:2.3:o:tenda:f1202_firmware:1.0br:~::~~::~~:::            |       |                 |                  |     |     |     |
| cpe:2.3:o:tenda:f1202_firmware:1.2.0.20\ (408\):~::~~::~~::: |       |                 |                  |     |     |     |
| cpe:2.3:h:tenda:fh1202:-:~::~~::~~:::                        |       |                 |                  |     |     |     |
| cpe:2.3:o:tenda:fh1202_firmware:1.2.0.19_en:~::~~::~~:::     |       |                 |                  |     |     |     |

No vendor comments have been submitted for this CVE

[← Previous ID](#)

Next ID→

© CVE.report 2023   |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](https://status.cve.report)