



# CVE-2023-37717

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

## Summary

<b>CVE</b>	CVE-2023-37717
<b>State</b>	PUBLIC
<b>Assigner</b>	cve@mitre.org
<b>Source Priority</b>	CVE Program / NVD first with legacy fallback
<b>Published</b>	2023-07-14 00:15:00 UTC
<b>Updated</b>	2023-07-21 14:31:00 UTC
<b>Description</b>	Tenda F1202 V1.0BR_V1.2.0.20(408) and FH1202_V1.2.0.19_EN, AC10 V1.0, AC1206 V1.0, AC7 V1.0, AC5 V1.0, and AC

## Risk And Classification

**Problem Types:** CWE-787

## NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	<a href="#">Tenda</a>	<a href="#">Ac10</a>	-	All	All	All
Operating System	<a href="#">Tenda</a>	<a href="#">Ac10 Firmware</a>	1.0	All	All	All
Hardware	<a href="#">Tenda</a>	<a href="#">Ac1206</a>	-	All	All	All
Operating System	<a href="#">Tenda</a>	<a href="#">Ac1206 Firmware</a>	1.0	All	All	All
Hardware	<a href="#">Tenda</a>	<a href="#">Ac5</a>	-	All	All	All
Operating System	<a href="#">Tenda</a>	<a href="#">Ac5 Firmware</a>	1.0	All	All	All
Hardware	<a href="#">Tenda</a>	<a href="#">Ac7</a>	-	All	All	All
Operating System	<a href="#">Tenda</a>	<a href="#">Ac7 Firmware</a>	1.0	All	All	All
Hardware	<a href="#">Tenda</a>	<a href="#">Ac9</a>	-	All	All	All
Operating System	<a href="#">Tenda</a>	<a href="#">Ac9 Firmware</a>	3.0	All	All	All
Hardware	<a href="#">Tenda</a>	<a href="#">F1202</a>	-	All	All	All
Operating System	<a href="#">Tenda</a>	<a href="#">F1202 Firmware</a>	1.0br	All	All	All
Operating System	<a href="#">Tenda</a>	<a href="#">F1202 Firmware</a>	1.2.0.20(408\)	All	All	All
Hardware	<a href="#">Tenda</a>	<a href="#">Fh1202</a>	-	All	All	All
Operating System	<a href="#">Tenda</a>	<a href="#">Fh1202 Firmware</a>	1.2.0.19_en	All	All	All

## References

Reference	Source	Link	Tags
Tenda Router Vulnerability on fromDhcpListClient function	MISC	<a href="#">github.com</a>	
CVE Program record	CVE.ORG	<a href="#">www.cve.org</a>	canonical
NVD vulnerability detail	NVD	<a href="#">nvd.nist.gov</a>	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

© [CVE.report](#) 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

**Free CVE JSON API** [cve.report/api](#)

**CVE.report and Source URL Uptime Status** [status.cve.report](#)