



CVE-2023-40901

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2023-40901
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2023-08-24 18:15:00 UTC
Updated	2023-08-30 22:15:00 UTC
Description	Tenda AC10 v4 US_AC10V4.0si_V16.03.10.13_cn was discovered to contain a stack overflow via parameter macFilterType

Risk And Classification

Problem Types: CWE-787

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tenda	Ac10v4	-	All	All	All
Operating System	Tenda	Ac10v4 Firmware	16.03.10.13	All	All	All

References

Reference	Source	Link	Tags
Affected Version	MISC	github.com	
founded-0-days/ac10/formSetMacFilterCfg/1.md at main · peris-navince/founded-0-days · GitHub	MISC	github.com	
NVD - CVE-2023-40901	MISC	nvd.nist.gov	
CVE Program record	CVE.ORG	www.cve.org	canonical

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)