



CVE-2023-44022

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2023-44022
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2023-09-27 15:19:00 UTC
Updated	2023-09-27 18:46:00 UTC
Description	Tenda AC10U v1.0 US_AC10UV1.0RTL_V15.03.06.49_multi_TDE01 was discovered to contain a stack overflow via the sp

Risk And Classification

Problem Types: CWE-119

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tendacn	Ac10u	1.0	All	All	All
Operating System	Tendacn	Ac10u Firmware	15.03.06.49_multi_tde01	All	All	All

References

Reference

Tenda AC10U v1.0 US_AC10UV1.0RTL_V15.03.06.49_multi_TDE01 were discovered to contain a stack overflow via the speed_dir paramete

[CVE Program record](#)

[NVD vulnerability detail](#)

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report