



CVE-2023-46556


Published on: Not Yet Published

Last Modified on: 10/27/2023 10:00:00 PM UTC

CVE-2023-46556

[Source: Mitre](#)[Source: NIST](#)[CVE.ORG](#)[Print: PDF](#)

CVSS:31/AV:N/AC:L/PR:N/UI:N/S:U/C:H/I:H/A:H



Certain versions of [X2000r](#) from [Totolink](#) contain the following vulnerability:

TOTOLINK X2000R Gh v1.0.0-B20230221.0948.web was discovered to contain a stack overflow via the function formFilter.

CVE-2023-46556 has been assigned by [M](#) cve@mitre.org to track the vulnerability - currently rated as **CRITICAL** severity.

CVSS3 Score: **9.8 - CRITICAL**

Attack
Vector

Attack
Complexity

Privileges
Required

User
Interaction

NETWORK

LOW

NONE

NONE

Scope

Confidentiality
Impact

Integrity
Impact

Availability
Impact

UNCHANGED

HIGH

HIGH

HIGH

CVE References

Description

Tags

Link

0. Vulnerability Introduction

[github.com](#)
[text/plain](#)

[MISC](#)
[github.com/XIYIM/Digging/blob/main/TOTOLINK/X2000R/4/1.md](#)

TOTOLINK全球领先的无线路由器,无线中继器研发
制造厂商

[totolink.cn](#)
[text/html](#)

[T MISC totolink.cn/home/menu/detail.html?menu_listtpl=download&id=85&ids=36](#)

By selecting these links, you may be leaving CVEreport webspace. We have provided these links to other websites because they may have information that would be of interest to you. No inferences should be drawn on account of other sites being referenced, or not, from this page. There may be other websites that are more appropriate for your purpose. CVEreport does not necessarily endorse the views expressed, or concur with the facts presented on these sites. Further, CVEreport does not endorse any commercial products that may be mentioned on these sites. Please address comments about any linked pages to [comment@cve.report](#).

There are currently no QIDs associated with this CVE

Known Affected Configurations (CPE V2.3)						
Type	Vendor	Product	Version	Update	Edition	Language
Hardware 	Totolink	X2000r	-	All	All	All
Operating System	Totolink	X2000r Firmware	1.0.0-b20230221.0948	All	All	All
cpe:2.3:h:totolink:x2000r:-:~::~~::~~::~~::~~::~~::~~:::						
cpe:2.3:o:totolink:x2000r_firmware:1.0.0-b20230221.0948:~::~~::~~::~~::~~::~~::~~:::						
No vendor comments have been submitted for this CVE						
← Previous ID				Next ID →		