



CVE-2023-51035

[MITRE](#)[NVD](#)[CVE.ORG](#)[Print: PDF](#)

Summary

CVE	CVE-2023-51035
State	PUBLISHED
Assigner	Unknown
Source Priority	CVE Program / NVD first with legacy fallback
Published	2023-12-22 19:15:00 UTC
Updated	2024-01-03 03:15:00 UTC
Description	Description unavailable.

Risk And Classification

Problem Types: CWE-78

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Totolink	Ex1200l	-	All	All	All
Operating System	Totolink	Ex1200l Firmware	9.3.5u.6146_b20201023	All	All	All

References

Reference	Source	Link	Tags
815yang.github.io/2023/12/12/ex1200l/totolink_ex1200L_NTPSyncWithHost		815yang.github.io	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

© CVE.report 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web](#)

[site](#). This site includes MITRE data granted under the following [license](#).

CVE.report and Source URL Uptime Status [status.cve.report](#)