



CVE-2024-0578

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f_img.jpg\)](#)

Summary

CVE	CVE-2024-0578
State	PUBLISHED
Assigner	Unknown
Source Priority	CVE Program / NVD first with legacy fallback
Published	2024-01-16 16:15:00 UTC
Updated	2024-01-19 19:53:00 UTC
Description	Description unavailable.

Risk And Classification

Problem Types: CWE-121

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Totolink	Lr1200gb	-	All	All	All
Operating System	Totolink	Lr1200gb Firmware	9.1.0u.6619_b20230130	All	All	All

References

Reference	Source	Link	Tags
Page not found · GitHub · GitHub		github.com	Broken Link
CVE-2024-0578: Totolink LR1200GB cstecci.cgi UploadCustomModule stack-based overflow		vuldb.com	Third Party Advis
CVE-2024-0578: Totolink LR1200GB cstecci.cgi UploadCustomModule stack-based overflow		vuldb.com	Permissions Requi
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analys

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report