



LAN Code Execution on TP-Link Archer MR200, Archer C20, TL-WR850N and TL-WR845N

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2025-15551
State	PUBLISHED
Assigner	TPLink
Source Priority	CVE Program / NVD first with legacy fallback
Published	2026-02-05 18:16:09 UTC
Updated	2026-04-22 22:16:28 UTC
Description	The response coming from TP-Link Archer MR200 v5.2, C20 v5 and v6, TL-WR850N v3, and TL-WR845N v4 for any request

Risk And Classification

Primary CVSS: v4.0 5.9 MEDIUM from f23511db-6c3e-4e32-a477-6aa17d310630

CVSS:4.0/AV:A/AC:L/AT:P/PR:N/UI:P/VC:H/VI:L/VA:L/SC:N/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

EPSS: 0.000320000 probability, percentile 0.094120000 (date 2026-04-22)

Problem Types: CWE-95 | CWE-95 CWE-95 Improper Neutralization of Directives in Dynamically Evaluated Code ('Eval Injection')

Version	Source	Type	Score	Severity	Vector
4.0	f23511db-6c3e-4e32-a477-6aa17d310630	Secondary	5.9	MEDIUM	CVSS:4.0/AV:A/AC:L/AT:P/PR:N/UI:P/VC:H/VI:L/VA:L/SC:N/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X
4.0	CNA	CVSS	5.9	MEDIUM	CVSS:4.0/AV:A/AC:L/AT:P/PR:N/UI:P/VC:H/VI:L/VA:L/SC:N/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X
3.1	nvd@nist.gov	Primary	5.6	MEDIUM	CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:L/I:L/A:L

CVSS v4.0 Breakdown

Attack Vector

Adjacent

Attack Complexity

Low

Attack Requirements

Present

Privileges Required

None

User Interaction

Passive

Confidentiality

High

Integrity

Low

Availability

Low

Sub Conf.

None

Sub Integrity

None

Sub Availability

None

CVSS:4.0/AV:A/AC:L/AT:P/PR:N/UI:P/VC:H/VI:L/VA:L/SC:N/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MS:C:X/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

CVSS v3.1 Breakdown

Attack Vector

Network

Attack Complexity

High

Privileges Required

None

User Interaction

None

Scope

Unchanged

Confidentiality

Low

Integrity

Low

Availability

Low

CVSS:3.1/AV:N/AC:H/PR:N/UI:N/S:U/C:L/I:L/A:L

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Hardware	Tp-link	Archer C20	6	All	All	All
Operating System	Tp-link	Archer C20 Firmware	All	All	All	All
Hardware	Tp-link	Archer Mr200	5.20	All	All	All

Operating System	Tp-link	Archer Mr200 Firmware	All	All	All	All
Hardware	Tp-link	TI-wr845n	4	All	All	All
Operating System	Tp-link	TI-wr845n Firmware	All	All	All	All
Hardware	Tp-link	TI-wr850n	3	All	All	All
Operating System	Tp-link	TI-wr850n Firmware	All	All	All	All

Vendor Declared Affected Products

Source	Vendor	Product	Version	Platforms
CNA	TP-Link Systems Inc.	Archer MR200 V5.2	affected 1.2.0 Build 250917 Rel.51746 custom	Not specified
CNA	TP-Link Systems Inc.	Archer C20 V6	affected 0.9.1 4.19 v0001.0 Build 250630 Rel.56583n custom	Not specified
CNA	TP Link Systems Inc.	TL-WR850N V3	affected 3.16.0 0.9.1 v6031.0 Build 251205 Rel.22089n custom	Not specified
CNA	TP Link Systems Inc.	TL-WR845N V4	affected 0.9.1 3.19 Build 251031 rel33710 custom	Not specified
CNA	TP-Link Systems Inc.	Archer C20 V5	affected US_V5_260419 custom	Not specified
CNA	TP-Link Systems Inc.	Archer C20 V5	affected EU_V5_260317 custom	Not specified

References

Reference	Source	Link	Tags
www.tp-link.com/en/support/download/archer-c20/v6	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	Product
www.tp-link.com/us/support/download/archer-c20/v5	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	
www.tp-link.com/in/support/download/archer-mr200/v5.20	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	Product
www.tp-link.com/us/support/faq/4948	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	Vendor Advisory
www.tp-link.com/in/support/download/tl-wr850n	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	Product
www.tp-link.com/en/support/download/archer-mr200/v5.20	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	Product
www.tp-link.com/en/support/download/archer-c20/v5	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	
www.tp-link.com/in/support/download/archer-c20/v6	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	Product
www.tp-link.com/in/support/download/tl-wr845n	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	Product
www.tp-link.com/en/support/download/tl-wr845n	f23511db-6c3e-4e32-a477-6aa17d310630	www.tp-link.com	Product
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analy

Vendor Comments And Credit

Discovery Credit

CNA: Swaroop Dora, Deven Lunkad, Ashutosh Kumar, and S. Venkatesan from IoT Security Research Lab, Indian Institute of Information Technology, Allahabad (en)

There are currently no legacy QID mappings associated with this CVE.

© [CVE.report](#) 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API [cve.report/api](#)

CVE.report and Source URL Uptime Status [status.cve.report](#)