



CVE-2025-40833

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f_img.jpg\)](#)

Summary

CVE	CVE-2025-40833
State	PUBLISHED
Assigner	siemens
Source Priority	CVE Program / NVD first with legacy fallback
Published	2026-05-12 10:16:41 UTC
Updated	2026-05-12 14:19:41 UTC
Description	The affected devices contain a null pointer dereference vulnerability while processing specially crafted IPv4 requests. This c

Risk And Classification

Primary CVSS: v4.0 8.7 HIGH from productcert@siemens.com

CVSS:4.0/AV:N/AC:L/AT:N/PR:N/UI:N/VC:N/VI:N/VA:H/SC:N/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

EPSS: 0.000400000 probability, percentile 0.120620000 (date 2026-05-12)

Problem Types: CWE-476 | CWE-476 CWE-476: NULL Pointer Dereference

Version	Source	Type	Score	Severity	Vector
4.0	productcert@siemens.com	Secondary	8.7	HIGH	CVSS:4.0/AV:N/AC:L/AT:N/PR:N/UI:N/VC:N/VI:N/VA:H/SC:N/SI:N/S
4.0	CNA	DECLARED	8.7	HIGH	CVSS:4.0/AV:N/AC:L/AT:N/PR:N/UI:N/VC:N/VI:N/VA:H/SC:N/SI:N/S
3.1	productcert@siemens.com	Primary	7.5	HIGH	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H
3.1	CNA	DECLARED	7.5	HIGH	CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

CVSS v4.0 Breakdown

Attack Vector

Network

Attack Complexity

Low

Attack Requirements

None

Privileges Required

None

User Interaction

None

None

Confidentiality

None

Integrity

None

Availability

High

Sub Conf.

None

Sub Integrity

None

Sub Availability

None

CVSS:4.0/AV:N/AC:L/AT:N/PR:N/UI:N/VC:N/VI:N/VA:H/SC:N/SI:N/SA:N/E:X/CR:X/IR:X/AR:X/MAV:X/MAC:X/MAT:X/MPR:X/MUI:X/MVC:X/MVI:X/MVA:X/MSX/MSI:X/MSA:X/S:X/AU:X/R:X/V:X/RE:X/U:X

CVSS v3.1 Breakdown

Attack Vector

Network

Attack Complexity

Low

Privileges Required

None

User Interaction

None

Scope

Unchanged

Confidentiality

None

Integrity

None

Availability

High

CVSS:3.1/AV:N/AC:L/PR:N/UI:N/S:U/C:N/I:N/A:H

Vendor Declared Affected Products

Source	Vendor	Product	Version	Platforms
CNA	Siemens	IE/PB LINK HA	affected * custom	Not specified
CNA	Siemens	IE/PB Link PN IO	affected * custom	Not specified
CNA	Siemens	RUGGEDCOM RM1224 LTE4G EU	affected V8.3 custom	Not specified
CNA	Siemens	RUGGEDCOM RM1224 LTE4G NAM	affected V8.3 custom	Not specified

CNA	Siemens	SCALANCE M804PB	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M812-1 ADSL-Router	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M812-1 ADSL-Router	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M816-1 ADSL-Router	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M816-1 ADSL-Router	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M826-2 SHDSL-Router	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M874-2	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M874-3	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M874-3 3G-Router CN	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M876-3	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M876-3 ROK	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M876-4	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M876-4 EU	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE M876-4 NAM	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUB852-1 A1	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUB852-1 B1	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUM853-1 A1	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUM853-1 B1	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUM853-1 EU	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUM856-1 A1	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUM856-1 B1	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUM856-1 CN	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUM856-1 EU	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE MUM856-1 RoW	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE S615 EEC LAN-Router	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE S615 LAN-Router	affected V8.3 custom	Not specified
CNA	Siemens	SCALANCE SC622-2C	affected * custom	Not specified
CNA	Siemens	SCALANCE SC626-2C	affected * custom	Not specified
CNA	Siemens	SCALANCE SC632-2C	affected * custom	Not specified
CNA	Siemens	SCALANCE SC636-2C	affected * custom	Not specified
CNA	Siemens	SCALANCE SC642-2C	affected * custom	Not specified
CNA	Siemens	SCALANCE SC646-2C	affected * custom	Not specified
CNA	Siemens	SCALANCE W1748-1 M12	affected * custom	Not specified
CNA	Siemens	SCALANCE W1748-1 M12	affected * custom	Not specified
CNA	Siemens	SCALANCE W1788-1 M12	affected * custom	Not specified
CNA	Siemens	SCALANCE W1788-1 M12	affected * custom	Not specified

CNA	Siemens	SCALANCE W786-2 SFP	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W786-2 SFP	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W786-2IA RJ45	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W786-2IA RJ45	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-1 M12	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-1 M12	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-1 RJ45	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-1 RJ45	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-2 M12	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-2 M12	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-2 M12 EEC	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-2 M12 EEC	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-2 M12 EEC	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-2 RJ45	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-2 RJ45	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE W788-2 RJ45	affected V6.6.0 custom	Not specified
CNA	Siemens	SCALANCE WAB762-1	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WAM763-1	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WAM763-1 ME	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WAM763-1 US	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WAM766-1	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WAM766-1 ME	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WAM766-1 US	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WAM766-1 EEC	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WAM766-1 EEC ME	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WAM766-1 EEC US	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WUB762-1	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WUB762-1 IFeatures	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WUM763-1	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WUM763-1	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WUM763-1 US	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WUM763-1 US	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WUM766-1	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WUM766-1 ME	affected V3.2.0 custom	Not specified
CNA	Siemens	SCALANCE WUM766-1 USA	affected V3.2.0 custom	Not specified

CNA	Siemens	SCALANCE X204-2	affected * custom	Not specified
CNA	Siemens	SCALANCE X204-2FM	affected * custom	Not specified
CNA	Siemens	SCALANCE X204-2LD	affected * custom	Not specified
CNA	Siemens	SCALANCE X204-2LD TS	affected * custom	Not specified
CNA	Siemens	SCALANCE X204-2TS	affected * custom	Not specified
CNA	Siemens	SCALANCE X206-1	affected * custom	Not specified
CNA	Siemens	SCALANCE X206-1LD	affected * custom	Not specified
CNA	Siemens	SCALANCE X208	affected * custom	Not specified
CNA	Siemens	SCALANCE X208PRO	affected * custom	Not specified
CNA	Siemens	SCALANCE X212-2	affected * custom	Not specified
CNA	Siemens	SCALANCE X212-2LD	affected * custom	Not specified
CNA	Siemens	SCALANCE X216	affected * custom	Not specified
CNA	Siemens	SCALANCE X224	affected * custom	Not specified
CNA	Siemens	SCALANCE X302-7 EEC 230V Coated	affected * custom	Not specified
CNA	Siemens	SCALANCE X302-7 EEC 230V	affected * custom	Not specified
CNA	Siemens	SCALANCE X302-7 EEC 24V Coated	affected * custom	Not specified
CNA	Siemens	SCALANCE X302-7 EEC 24V	affected * custom	Not specified
CNA	Siemens	SCALANCE X302-7 EEC 2x 230V Coated	affected * custom	Not specified
CNA	Siemens	SCALANCE X302-7 EEC 2x 230V	affected * custom	Not specified
CNA	Siemens	SCALANCE X302-7 EEC 2x 24V Coated	affected * custom	Not specified
CNA	Siemens	SCALANCE X302-7 EEC 2x 24V	affected * custom	Not specified
CNA	Siemens	SCALANCE X304-2FE	affected * custom	Not specified
CNA	Siemens	SCALANCE X306-1LD FE	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-2 EEC 230V Coated	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-2 EEC 230V	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-2 EEC 24V Coated	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-2 EEC 24V	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-2 EEC 2x 230V Coated	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-2 EEC 2x 230V	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-2 EEC 2x 24V Coated	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-2 EEC 2x 24V	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-3	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-3	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-3LD	affected * custom	Not specified
CNA	Siemens	SCALANCE X307-3LD	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2	affected * custom	Not specified

CNA	Siemens	SCALANCE X308-2	affected * custom	not specified
CNA	Siemens	SCALANCE X308-2 RD Inkl. SIPLUS Variants	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2LD	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2LD	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2LH	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2LH	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2LH	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2LH	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2M	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2M	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2M PoE	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2M PoE	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2M TS	affected * custom	Not specified
CNA	Siemens	SCALANCE X308-2M TS	affected * custom	Not specified
CNA	Siemens	SCALANCE X310	affected * custom	Not specified
CNA	Siemens	SCALANCE X310	affected * custom	Not specified
CNA	Siemens	SCALANCE X310FE	affected * custom	Not specified
CNA	Siemens	SCALANCE X310FE	affected * custom	Not specified
CNA	Siemens	SCALANCE X320-1 FE	affected * custom	Not specified
CNA	Siemens	SCALANCE X320-1-2LD FE	affected * custom	Not specified
CNA	Siemens	SCALANCE X408-2	affected * custom	Not specified
CNA	Siemens	SCALANCE XF204	affected * custom	Not specified
CNA	Siemens	SCALANCE XF204-2	affected * custom	Not specified
CNA	Siemens	SCALANCE XF206-1	affected * custom	Not specified
CNA	Siemens	SCALANCE XF208	affected * custom	Not specified
CNA	Siemens	SCALANCE XM408-4C	affected * custom	Not specified
CNA	Siemens	SCALANCE XM408-4C L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XM408-8C	affected * custom	Not specified
CNA	Siemens	SCALANCE XM408-8C L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XM416-4C	affected * custom	Not specified
CNA	Siemens	SCALANCE XM416-4C L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XR324-12M 230V Ports On Front	affected * custom	Not specified
CNA	Siemens	SCALANCE XR324-12M 230V Ports On Front	affected * custom	Not specified
CNA	Siemens	SCALANCE XR324-12M 230V Ports On Rear	affected * custom	Not specified
CNA	Siemens	SCALANCE XR324-12M 230V Ports On Rear	affected * custom	Not specified
CNA	Siemens	SCALANCE XR324-12M 24V Ports On Front	affected * custom	Not specified

CNA	Siemens	SCALANCE XR524-8C 2x230V	affected * custom	Not specified
CNA	Siemens	SCALANCE XR524-8C 2x230V L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XR526-8C 1x230V	affected * custom	Not specified
CNA	Siemens	SCALANCE XR526-8C 1x230V L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XR526-8C 24V	affected * custom	Not specified
CNA	Siemens	SCALANCE XR526-8C 24V L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XR526-8C 2x230V	affected * custom	Not specified
CNA	Siemens	SCALANCE XR526-8C 2x230V L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XR528-6M	affected * custom	Not specified
CNA	Siemens	SCALANCE XR528-6M 2HR2 L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XR528-6M 2HR2	affected * custom	Not specified
CNA	Siemens	SCALANCE XR528-6M L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XR552-12M	affected * custom	Not specified
CNA	Siemens	SCALANCE XR552-12M 2HR2 L3 Int.	affected * custom	Not specified
CNA	Siemens	SCALANCE XR552-12M 2HR2	affected * custom	Not specified
CNA	Siemens	SCALANCE XR552-12M 2HR2	affected * custom	Not specified
CNA	Siemens	SIMATIC CFU DIQ	affected V2.0.0 custom	Not specified
CNA	Siemens	SIMATIC CFU PA	affected V2.0.0 custom	Not specified
CNA	Siemens	SIMATIC CFU PA	affected V2.0.0 custom	Not specified
CNA	Siemens	SIMATIC ET 200pro IM 154-8 PN/DP CPU	affected * custom	Not specified
CNA	Siemens	SIMATIC ET 200pro IM 154-8F PN/DP CPU	affected * custom	Not specified
CNA	Siemens	SIMATIC ET 200pro IM 154-8FX PN/DP CPU	affected * custom	Not specified
CNA	Siemens	SIMATIC ET 200S IM 151-8 PN/DP CPU	affected * custom	Not specified
CNA	Siemens	SIMATIC ET 200S IM 151-8F PN/DP CPU	affected * custom	Not specified
CNA	Siemens	SIMATIC ET 200SP CPU 1510SP F-1 PN	affected * custom	Not specified
CNA	Siemens	SIMATIC ET 200SP CPU 1510SP-1 PN	affected * custom	Not specified
CNA	Siemens	SIMATIC ET 200SP CPU 1512SP F-1 PN	affected * custom	Not specified
CNA	Siemens	SIMATIC ET 200SP CPU 1512SP-1 PN	affected * custom	Not specified
CNA	Siemens	SIMATIC ET 200SP HA IM155-6 PN	affected V1.3 custom	Not specified
CNA	Siemens	SIMATIC S7-1500 CPU 1511-1 PN	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-1500 CPU 1511F-1 PN	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-1500 CPU 1513-1 PN	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-1500 CPU 1515-2 PN	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-1500 CPU 1515F-2 PN	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-1500 CPU 1516-3 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-1500 CPU 1516F-3 PN/DP	affected * custom	Not specified

CNA	Siemens	SIMATIC S7-300 CPU 314C-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 314C-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 315-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 315F-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 315T-3 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 317-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 317F-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 317T-3 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 317TF-3 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 319-3 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-300 CPU 319F-3 PN/DP	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-400 CPU 412-2 PN V7	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-400 CPU 414-3 PN/DP V7	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-400 CPU 414F-3 PN/DP V7	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-400 CPU 416-3 PN/DP V7	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-400 CPU 416F-3 PN/DP V7	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-400 H V6 CPU Family Incl. SIPLUS Variants	affected * custom	Not specified
CNA	Siemens	SIMATIC S7-410 V10 CPU Family Incl. SIPLUS Variants	affected V10.2 custom	Not specified
CNA	Siemens	SIMATIC S7-410 V8 CPU Family Incl. SIPLUS Variants	affected V8.3 custom	Not specified
CNA	Siemens	SIMIT UNIT V10	affected * custom	Not specified
CNA	Siemens	SIMIT UNIT V11	affected * custom	Not specified
CNA	Siemens	SINAMICS CBE20	affected * custom	Not specified
CNA	Siemens	SINAMICS G115D	affected * custom	Not specified
CNA	Siemens	SINAMICS G120 Incl. SIPLUS Variants	affected * custom	Not specified
CNA	Siemens	SINAMICS G120C	affected * custom	Not specified
CNA	Siemens	SINAMICS G120D	affected * custom	Not specified
CNA	Siemens	SINAMICS G120X	affected * custom	Not specified
CNA	Siemens	SINAMICS G120XA	affected * custom	Not specified
CNA	Siemens	SINAMICS G130	affected * custom	Not specified
CNA	Siemens	SINAMICS G150	affected * custom	Not specified
CNA	Siemens	SINAMICS S110	affected * custom	Not specified
CNA	Siemens	SINAMICS S120 Incl. SIPLUS Variants	affected * custom	Not specified
CNA	Siemens	SINAMICS S150	affected * custom	Not specified
CNA	Siemens	SINUMERIK 840D SI	affected * custom	Not specified
CNA	Siemens	SIPLUS ET 200S IM 151-8 PN/DP CPU	affected * custom	Not specified
CNA	Siemens	SIPLUS ET 200S IM 151-8F PN/DP CPU	affected * custom	Not specified

CNA	Siemens	SIPLUS NET IE/PB Link PN IO	affected * custom	Not specified
CNA	Siemens	SIPLUS S7-300 CPU 314C-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIPLUS S7-300 CPU 315-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIPLUS S7-300 CPU 315F-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIPLUS S7-300 CPU 317-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIPLUS S7-300 CPU 317F-2 PN/DP	affected * custom	Not specified
CNA	Siemens	SIPLUS S7-400 CPU 414-3 PN/DP V7	affected * custom	Not specified
CNA	Siemens	SIPLUS S7-400 CPU 416-3 PN/DP V7	affected * custom	Not specified
CNA	Siemens	SITOP PSU8600 1AC 20 A/4x5 A PN	affected * custom	Not specified
CNA	Siemens	SITOP PSU8600 3AC 20 A PN	affected * custom	Not specified
CNA	Siemens	SITOP PSU8600 3AC 20 A/4x5 A PN	affected * custom	Not specified
CNA	Siemens	SITOP PSU8600 3AC 40 A PN	affected * custom	Not specified
CNA	Siemens	SITOP PSU8600 3AC 40 A/4x10 A PN	affected * custom	Not specified
CNA	Siemens	SITOP PSU8600 3AC 40 A/4x10A EIP	affected * custom	Not specified
CNA	Siemens	SITOP UPS1600 10 A Ethernet/ PROFINET	affected * custom	Not specified
CNA	Siemens	SITOP UPS1600 20 A Ethernet/ PROFINET	affected * custom	Not specified
CNA	Siemens	SITOP UPS1600 40 A Ethernet/ PROFINET	affected * custom	Not specified
CNA	Siemens	SITOP UPS1600 EX 20 A Ethernet PROFINET	affected * custom	Not specified

References

Reference	Source	Link	Tags
cert-portal.siemens.com/productcert/html/ssa-392349.html	productcert@siemens.com	cert-portal.siemens.com	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

© CVE.report 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](https://www.mitre.org) and the authoritative source of CVE content is [MITRE's CVE web site](https://www.mitre.org/cve). This site includes MITRE data granted under the following [license](https://www.mitre.org/cve).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report