



Stored Cross-Site Scripting in Link Aggregation Name Handling

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF](#)

Summary

CVE	CVE-2026-22322
State	PUBLISHED
Assigner	CERTVDE
Source Priority	CVE Program / NVD first with legacy fallback
Published	2026-03-18 08:16:30 UTC
Updated	2026-04-27 19:22:08 UTC
Description	A stored cross-site scripting (XSS) vulnerability in the Link Aggregation configuration interface allows an unauthenticated re

Risk And Classification

Primary CVSS: v3.1 7.1 HIGH from info@cert.vde.com

CVSS: 3.1/AV:N/AC:L/PR:N/UI:R/S:C/C:L/I:L/A:L

EPSS: 0.000300000 probability, percentile 0.084520000 (date 2026-04-27)

Problem Types: CWE-79 | CWE-79 CWE-79 Improper Neutralization of Input During Web Page Generation ('Cross-site Scripting')

Version	Source	Type	Score	Severity	Vector
3.1	info@cert.vde.com	Primary	7.1	HIGH	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:C/C:L/I:L/A:L
3.1	CNA	CVSS	7.1	HIGH	CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:C/C:L/I:L/A:L

CVSS v3.1 Breakdown

Attack Vector

Network

Attack Complexity

Low

Privileges Required

None

User Interaction

Required

Scope

Changed

Confidentiality

Low

Integrity

Low

Availability

Low

CVSS:3.1/AV:N/AC:L/PR:N/UI:R/S:C/C:L/I:L/A:L

Vendor Declared Affected Products

Source	Vendor	Product	Version	Platforms
CNA	Phoenix Contact	FL SWITCH 2005	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2008	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2016	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2105	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2108	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2116	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2204-2TC-2SFX	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2205	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2206-2FX	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2206-2FX SM	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2206-2FX SM ST	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2206-2FX ST	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2206-2SFX	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2206-2SFX PN	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2206C-2FX	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2207-FX	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2207-FX SM	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2208	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2208 PN	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2208C	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2212-2TC-2SFX	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2214-2FX	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2214-2FX SM	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2214-2SFX	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2214-2SFX PN	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2216	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2216 PN	affected 0.0.0 3.53 semver	Not specified

CNA	Phoenix Contact	FL NAT 2008	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL NAT 2208	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL NAT 2304-2GC-2SFP	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2008F	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2316/K1	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2506-2SFP/K1	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 2508/K1	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH TSN 2316	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH TSN 2312-2GC-2SFP	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH TSN 2314-2SFP	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 5924-4GC	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 5916-8GC-4SFP	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 5924SFP-4GC	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 5924-4SFP	affected 0.0.0 3.53 semver	Not specified
CNA	Phoenix Contact	FL SWITCH 5916SFP-8GC-4SFP	affected 0.0.0 3.53 semver	Not specified

References

Reference	Source	Link	Tags
certvde.com/de/advisories/VDE-2025-104	info@cert.vde.com	certvde.com	
CVE Program record	CVE.ORG	www.cve.org	canonical
NVD vulnerability detail	NVD	nvd.nist.gov	canonical, analysis

Vendor Comments And Credit

Discovery Credit

CNA: Gabriele Quagliarella from Nozomi Networks (en)

There are currently no legacy QID mappings associated with this CVE.

© [CVE.report](#) 2026 |

Use of this information constitutes acceptance for use in an AS IS condition. There are NO warranties, implied or otherwise, with regard to this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API cve.report/api

CVE.report and Source URL Uptime Status status.cve.report