



CVE-2016-2398

[MITRE](#)[NVD](#)[CVE.ORG](#)[JSON API](#)[Print: PDF !\[\]\(003082e50e3009141f59bd5df831749f_img.jpg\)](#)

Summary

CVE	CVE-2016-2398
State	PUBLIC
Assigner	cve@mitre.org
Source Priority	CVE Program / NVD first with legacy fallback
Published	2016-02-17 16:59:00 UTC
Updated	2016-03-04 14:40:00 UTC
Description	Comcast XFINITY Home Security System does not properly maintain base-station communication, which allows physically

Risk And Classification

Problem Types: CWE-254

NVD Known Affected Configurations (CPE 2.3)

Type	Vendor	Product	Version	Update	Edition	Language
Operating System	Comcast	Xfinity Home Security System	All	All	All	All
Operating System	Comcast	Xfinity Home Security System	All	All	All	All

References

Reference	Source
R7-2015-23: Comcast XFINITY Home Security Syste... Rapid7 Community and Blog	MISC
Vulnerability Note VU#418072 - Comcast XFINITY Home Security fails to properly handle wireless communications disruption	CERT-VN
Xfinity's Security System Flaws Open Homes to Thieves WIRED	MISC
CVE Program record	CVE.ORG
NVD vulnerability detail	NVD

No vendor comments have been submitted for this CVE.

There are currently no legacy QID mappings associated with this CVE.

this information or its use. Any use of this information is at the user's risk. It is the responsibility of user to evaluate the accuracy, completeness or usefulness of any information, opinion, advice or other content. EACH USER WILL BE SOLELY RESPONSIBLE FOR ANY consequences of his or her direct or indirect use of this web site. ALL WARRANTIES OF ANY KIND ARE EXPRESSLY DISCLAIMED. This site will NOT BE LIABLE FOR ANY DIRECT, INDIRECT or any other kind of loss.

CVE, CWE, and OVAL are registered trademarks of [The MITRE Corporation](#) and the authoritative source of CVE content is [MITRE's CVE web site](#). This site includes MITRE data granted under the following [license](#).

Free CVE JSON API [cve.report/api](#)

CVE.report and Source URL Uptime Status [status.cve.report](#)